

Mountain High Oxygen
2244 SE Airport Way, Suite 100
Redmond, Oregon 97756-7537

Phone 541-923-4100 Fax 541-923-4141

sales@mhoxygen.com www.mhoxygen.com



Technical Service Bulletin MHTSB-2022-01

Emergency Bypass Control Switch Upgrade

Dear Customer:

Our records indicate that you have purchased either a 2ip or 4ip Built-in Pulse Demand System from Mountain High Oxygen.

It has come to our attention that under some circumstances the Emergency Bypass oxygen circuit, once enabled, may not shut off again properly and oxygen will *continue* to flow *after* the control switch has been returned to the "OFF" position.

This behavior can be attributed to excessive restriction in the Emergency Bypass Control (EBC) switch exhaust-port filter fitting, and is alleviated by replacing the fitting with a less-restrictive one.

If you have experienced this problem, please return this form to Mountain High Oxygen and we will send you a replacement filter at no charge, along with instructions for performing the upgrade.

Sincerely,

Your MH Team

Note that this problem is also dependant on other aspects of your oxygen system (particularly control tubing length). While it is generally only experienced in especially "perverse" circumstances, if you are anticipating servicing your oxygen system you may wish to perform this upgrade at the same time in order to avoid this problem in the future.

re: Technical Service Bulletin MHTSB-2022-01

Yes, I have experienced this problem. Please send me the new Upgrade Kit & instructions.

Update my Contact Information as follows:

Name:					
Address					
City:		State:		Postal Code:	
E-mail:					
Phone:					